










-  7× Болт M10x130*
 -  7× Гайка M10*
 -  7× Шайба A10.5x20*
 -  2× CH-100-5,8m OC
- * - нержавеющая сталь





- 3× Болт M10x130*
 - 3× Болт M10x15*
 - 3× Гайка M10*
 - 3× Шайба A10.5x20*
 - 4× Анкер или S-BT (см. инструкцию)
 - 1× CH-100-5,8m OC
- * - нержавеющая сталь



- 3× Болт M10x8*
 - 3× Болт M10x15*
 - 3× Гайка M10*
 - 3× Шайба A10.5x20*
 - 4× Анкер или S-BT (см. инструкцию)
 - 1× CH-50x100-5,8m OC
- * - нержавеющая сталь

