











- 2× Болт M10x130\*
- 2× Гайка M10\*
- 2× Шайба A10.5x20\*
- 1× CH-100-5,8m OC
- \* - stainless steel

- 2× Гайка M12 или M16 ①
- 2× Шайба 13x40x3 или 17x40x3 ②
- 1× Шпилька M12 или M16 ③