








- 8× Болт M10 (A2-70 или 8.8)
- 8× Гайка M10 (A2-70 или 8)
- 8× Шайба A10.5x20 (A2 или Zn)
- 2× CH-100-5,8m OC / CH-50x100-5,8m OC





- 12× Болт М10 (А2-70 или 8.8) 12× Гайка М10 (А2-70 или 8)
- 12× Шайба А10.5х20 (А2 или Zn)
- 3× CH-100-5,8m OC / CH-50x100-5,8m OC

- 16× Болт М10 (А2-70 или 8.8) 16× Гайка М10 (А2-70 или 8)
- 16× Шайба А10.5х20 (А2 или Zn)
- 3× CH-100-5,8m OC / CH-50x100-5,8m OC



Профиль
CH-100-5,8m OC

Профиль
CH-50x100-5,8m OC

Н, мм	Л, мм	Болт
100	130	Болт М10х130
50	80	Болт М10х80